

WAYPOINT LIST (WGS84)

KUDOS ONE ALFA RNAV DEPARTURE (RWY05R) KUDOS ONE CHALI RNAV DEPARTURE (RWY05L)

Waypoint Name	Latitude	Longitude
TP050	250742.00N	1211712.00E
TP064	250648.00N	1211730.00E
NEPAS	251642.00N	1212854.00E
KUDOS	250753.00N	1215928.00E

Seq No	Path Terminator	Fix Identifier (Waypoint Name)	Fly Over	Course °M (°T)	Turn Direction	Altitude (ft)	Speed Limit (kt)	Vertical Angle	Nav Performance
KUDOS ONE ALFA RNAV DEPARTURE (RWY05R)									
01	VA	-	-	054 (049.2)	-	+600	-	-	RNAV 1
02	DF	TP064	Y	-	-	-	-	-	RNAV 1
03	TF	NEPAS	Y	051 (046.4)	-	+4500	-	-	RNAV 1
04	TF	KUDOS	-	112 (107.7)	-	-	-	-	RNAV 1
KUDOS ONE CHALI RNAV DEPARTURE (RWY05L)									
01	VA	-	-	054 (049.2)	-	+600	-	-	RNAV 1
02	DF	TP050	Y	-	-	-	-	-	RNAV 1
03	TF	NEPAS	Y	054 (049.8)	-	+4500	-	-	RNAV 1
04	TF	KUDOS	-	112 (107.7)	-	-	-	-	RNAV 1

Sector	DME Gap	Critical DME
KUDOS ONE ALFA RNAV DEPARTURE (RWY05R)		
RWY05R - TP064	Y	-
TP064 - NEPAS	Y	-
NEPAS - KUDOS	N	APU, HLG, TSI
KUDOS ONE CHALI RNAV DEPARTURE (RWY05L)		
RWY05L - TP050	Y	-
TP050 - NEPAS	Y	-
NEPAS - KUDOS	N	APU, HLG, TSI

DME Gap: Y means gap EXIST, N means NO gap.